

Contents

Explanation of frequently used symbols	XV	
1	General - Definition of the term "steel" -	
	Objectives in steelmaking	1
2	Thermodynamic principles	3
2.1	Overview of the most important reactions which take place during the refining stage	3
2.2	Activities in metallic polynary (multiphase) systems	6
2.3	Structure of the slags	9
2.4	Gas equilibria	14
2.5	Oxidation equilibria	19
2.5.1	The iron-oxygen system	19
2.5.2	Binary systems of slags of the oxidation reactions	23
2.5.2.1	The FeO-MnO system	24
2.5.2.2	The FeO-SiO ₂ system	26
2.5.2.3	The FeO-Fe ₂ O ₃ -CaO system	28
2.5.2.4	The FeO-Fe ₂ O ₃ -MgO system	34
2.5.2.5	The CaO-SiO ₂ and CaO-P ₂ O ₅ systems	35
2.5.3	The CaO-FeO _n -SiO ₂ ternary system and the associated metal-slag equilibria	37
2.5.4	The CaO-FeO _n -P ₂ O ₅ system and the dephosphorisation equilibrium	47
2.6	Deoxidation equilibria	54
2.6.1	Simple deoxidation equilibria	54
2.6.2	The formation of complex oxides	62
2.7	Desulphurisation equilibria	73
2.7.1	The solubility products of the sulphides	75
2.7.2	Desulphurisation with solid desulphurising agents	79
2.7.3	Desulphurisation with lime-rich basic slags	81
2.8	Equilibria with alkali-containing slags	91
2.9	Calcium metallurgy	98
3	Mass transfer	103
3.1	Reaction types in extractive metallurgy	103
3.1.1	Introduction and fundamental concepts	103
3.1.2	Reaction types	108
		IX

3.1.2.1	Consecutive reactions	108
3.1.2.2	Double-decomposition reactions	111
3.1.2.3	Reactions involving branch subreactions	116
3.2	Transport phenomena	119
3.2.1	Introduction and fundamental concepts	119
3.2.2	Boundary layers	121
3.2.3	Mass transfer with frictionless flow	123
3.2.4	Flow and mass transfer in the case of flow with friction, laminar flow	129
3.2.4.1	Equation for the velocity boundary layer in the case of forced laminar flow	129
3.2.4.2	Equation for the diffusion boundary layer under conditions of forced laminar flow	132
3.2.4.3	Solution of the boundary layer equations	133
3.2.5	Approximate calculation of the boundary layer equations with the aid of the integral profile method	140
3.2.5.1	The boundary layer at the longitudinally streamed plate	140
3.2.5.2	Flow and concentration boundary layers at a liquid-liquid interface .	142
3.2.6	Flow and mass transfer in the case of flow with friction, turbulent flow	150
3.2.6.1	Definition of turbulence	150
3.2.6.2	Reynolds shear stress	151
3.2.6.3	Prandtl's mixing length	154
3.2.6.4	Turbulent mass transfer	155
3.2.7	Turbulent momentum and mass transfer at free surfaces	157
3.2.8	Influence of interfacially active substances on mass transfer	162
3.2.9	Mass transfer with a precipitation reaction at the interface	164
4	The kinetics of metallurgical reactions	167
4.1	Introduction	167
4.2	Metal-gas reactions	168
4.2.1	The reaction between liquid iron and nitrogen	168
4.2.1.1	Determining the reaction scheme	168
4.2.1.2	Mass transport in the gas phase	170
4.2.1.3	Mass transport in the melt	173
4.2.1.4	The phase-boundary reaction at pure iron-nitrogen melts	175
4.2.1.5	Influence of oxygen and sulphur on nitrogen transfer	177
4.2.2	The reaction between liquid iron and hydrogen	179
4.2.3	The carbon-oxygen reaction in liquid iron	180
4.2.3.1	Oxidation of carbon at a free surface of the metal melt by a gaseous oxidation agent	181
4.2.3.2	Oxidation of liquid iron by oxygen	188
4.2.3.3	The carbon monoxide reaction	190
4.3	Metal-slag reactions	194
4.3.1	Reactions without participation of carbon	194
4.3.1.1	Transport-determined reactions	194

4.3.1.2	Phase-boundary reaction	196
4.3.2	Reactions involving carbon	199
4.4	Dissolution of solids	209
4.4.1	Dissolution of dense substances	209
4.4.1.1	Detachment of atoms from the crystal	209
4.4.1.2	Transport-controlled dissolution	212
4.4.2	Dissolution of porous substances	214
4.4.3	Dissolution of lime in siliceous slags	219
5	Laws governing the movement of solid particles, droplets and gas bubbles in multiphase systems	221
5.1	Introduction	221
5.2	Movement of solid particles	221
5.3	Movement of gas bubbles	225
5.3.1	Bubble formation	225
5.3.2	Drag laws relating to gas bubbles	232
5.3.3	Bubble disintegration	238
5.4	Movement of droplets	239
5.5	Movement laws relating to particle suspensions and bubble swarms	240
5.5.1	Movement of particle clouds of limited height	241
5.5.2	Bubble plumes	246
5.5.2.1	General	246
5.5.2.2	Bubble plumes in the converter	251
5.5.2.3	Bubble plumes in the ladle	253
5.6	Behaviour of particle-gas jets	266
5.6.1	Constitutional diagram of pneumatic conveying	267
5.6.2	Hydrodynamic behaviour of particle-gas jets	267
5.6.2.1	Types of particle-gas jets	267
5.6.2.2	Behaviour of coupled particle-gas jets upon penetration into melts	270
5.6.3	Penetration of particles into melts	277
5.6.3.1	Introduction	277
5.6.3.2	Penetration of a single particle	279
5.6.3.3	Subsequent behaviour of the particles in the melt, penetration of a particle cloud	282
5.7	Emulsification	284
5.7.1	Condition for droplet formation	285
5.7.2	Velocity at the slag-metal interface	287
5.7.3	The quantity of emulsified droplets	294
6	Mass transfer in metallurgical systems	297
6.1	Introduction	297
6.2	Wear of refractory material	298
6.3	Bubble-agitated interface	302
6.3.1	Model concepts	302
6.3.2	Experimental results	304
6.4	Fundamentals of mass transfer at particles, droplets and bubbles ...	309

6.5	Growth and dissolution of small particles in melts	309
6.6	Interaction between particles and interfaces; particle coagulation and particle separation	316
6.7	Particle separation by stirring	320
6.8	Mass transfer at solid particles in the case of higher Reynolds numbers	325
6.9	Mass transfer at particles, taking into account diffusion in the particle	328
6.10	Mass transfer between melts and droplets	335
6.11	Mass transfer between gas bubbles and melts	339
7	Reactor theory	343
7.1	The concept of reactor theory	343
7.2	Macrokinetics in homogeneous systems	345
7.2.1	Preliminary remarks	345
7.2.2	Macrokinetics in non-emulsified systems	346
7.2.2.1	Permanent phase contact	347
7.2.2.2	Transitory phase contact	349
7.2.3	Macrokinetics in emulsified systems	350
7.2.3.1	Permanent phase contact	351
7.2.3.2	Transitory phase contact	356
7.2.4	Conclusions	358
7.3	Mass transfer in dispersed systems	359
7.3.1	Rules for determining mass transfer at particles, droplets and bubbles	359
7.3.2	Metal-slag reactions in the oxygen converter	362
7.3.2.1	The oxygen converter reaction system	362
7.3.2.2	Particle size distribution, quantity and residence time of iron droplets emulsified in the slag	365
7.3.2.3	The dephosphorisation reaction	366
7.3.2.4	Influence of changing parameters	376
7.3.3	Desulphurisation of hot metal by the injection of lime or calcium carbide	378
7.3.3.1	Analysis of the desulphurisation reaction involving lime	378
7.3.3.2	Desulphurisation with calcium carbide	384
7.4	The decarburisation reaction	384
7.5	Mixing	395
7.5.1	Introduction	395
7.5.2	Mixing models	398
7.5.2.1	Model for turbulent circulatory flow	398
7.5.2.2	Simple circulation model	399
7.5.2.3	Tank-in-series model	401
7.5.2.4	Two-tank model	405
7.5.2.5	Combined circulation and two-tank model	408
7.5.2.6	Generalised zonal model	412
7.5.3	Mixing in the converter	412

8	The kinetics of melting	417
8.1	Melting down with direct heat transfer from the energy source to the solid material	417
8.1.1	Introduction	417
8.1.2	Preheating period	421
8.1.3	Fusion period	427
8.2	Meltdown of a solid in its own melt	432
8.2.1	Introduction	432
8.2.2	Description of the melting process without taking into account heat conduction in the solid	436
8.2.2.1	Isothermal melting of a solid at melting temperature immersed in a slightly superheated bath	437
8.2.2.2	Adiabatic melting of a solid at melting temperature immersed in a slightly superheated bath	437
8.2.2.3	Isothermal melting of a solid already at melting temperature immersed in a highly superheated bath	440
8.2.2.4	Isothermal and adiabatic melting of a cold charge material having a heat conductivity of $\lambda' = 0$	442
8.2.2.5	Isothermal melting of a cold charge material having a heat conductivity of $\lambda' = \infty$	442
8.2.3	Description of the melting process taking into account heat conduction in the solid	444
8.2.4	Experimental results	449
8.3	Melting of pure iron in liquid iron-carbon alloys	451
8.4	Process model of melting	454
	References	457
	Index	491