

Dipl.-Ing. Gerd Reisner, Leoben

**Micromechanical Modeling
of Strain Induced Martensitic
Transformation in
Cu-Fe-Alloys and in Low
Alloyed TRIP-Steels**

Reihe **18**: Mechanik/
Bruchmechanik

Nr. **214**

Contents

1	Introduction	1
1.1	Aims and scope	1
1.2	Martensite	2
1.3	TRIP in steels	3
1.3.1	Metastable austenitic steels	3
1.3.2	Low alloyed TRIP steels	5
1.4	Notation and Definitions	7
2	Transformation criterion	9
2.1	The interface jump condition	9
2.2	The global energy balance	15
2.3	The transformation criterion for a microregion	16
3	SIMT in a dilute Cu-Fe alloy	21
3.1	Geometrical and material model	21
3.2	ESTIMATION OF THE TRANSFORMATION BARRIER	24
3.3	Results and discussion	26
4	SIMT in low alloyed TRIP steels	32
4.1	Material model	33
4.2	<i>Transformation criterion for TRIP-steels</i>	34
4.3	The stress free transformation strain	35
4.4	The load type sensitivity of SIMT	36
4.4.1	<i>Geometrical and material model</i>	36
4.4.2	Results and discussion	37
4.5	Randomness of the lattice orientation and SIMT	40
4.5.1	<i>The geometrical model</i>	40
4.5.2	Lattice orientation, texture and stress free transformation strain	41
4.5.3	Results and Discussion	42

5	Summary	47
A	Interaction work terms	49
B	Constitutive Relations and user subroutine UMAT	50
C	Discussion of flow behavior	53
	Bibliography	54